

Inspection Photos and Issue Report

7/1/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334752

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 1: Photos show cut slopes on the south end of the Location. Photo shows Operator appears to have placed additional soils to repair the erosion degradation, however control measures remain missing or insufficient to minimize erosion and degradation.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334752



Photo 2: Photo shows tank and bull plug where fluids have continued to leak from.