

Inspection Photos and Issue Report

7/1/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334682

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



Photo 1: Photos taken from the topsoil stockpiles. Photos examples showing areas that are predominantly cheat grass, and not progressing towards reclamation standards; unable to find evidence of additional reclamation work per corrective actions.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



July 1, 2022



July 1, 2022

Photo 2: Photos taken from the topsoil stockpiles. Photos examples showing areas that are predominantly cheat grass, and not progressing towards reclamation standards; unable to find evidence of additional reclamation work per corrective actions.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



Photo 3: Photos examples showing noxious weeds (musk thistle) established on the interim areas of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 334682



Photo 4: Photos examples showing noxious weeds (Field bindweed- white flowers) established on the location.