

# Inspection Photos and Issue Report

7/1/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 334983

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 334983



**Photo 1:** Photos show the inlet to the sediment trap on the north end of the Location. Photo shows control measure has not been installed per good engineering practices; gully erosion has been repaired, however soils have been left unconsolidated, and the inlet has not been properly engineered and armored.