

Inspection Photos and Issue Report

7/1/2022

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 311692

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



July 1, 2022



July 1, 2022

Photo 1: Photos shows the degradation has been repaired, and a hydromulch applied to the slope; it is noted that hydromulch is considered a temporary control. Pot-holes also appear to have been implemented on sections of the slope, though it is unclear if this is adequate or appropriate to stabilize the slopes.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311692



Photo 2: Photo taken from the northeastern-most tank. Stained soils appear to have been cleaned and Work at tank appears to be in process, however it is unclear if corrective actions have been addressed in its entirety; manway cover removed, pipes leading to tank have been disconnected; liner integrity beneath tank unknown.

