

Inspection Photos
Location Name: SRC Pratt pad
Location ID: 319098



Photo 1 Well heads and unused equipment (fencing)

Photo 2 production equipment

Inspection Photos
Location Name: SRC Pratt pad
Location ID: 319098



Photo 3 TNK BTRY



Photo 4 unreported leak or spill between produced water tank and crude oil tank. Stained soil

Inspection Photos
Location Name: SRC Pratt pad
Location ID: 319098



Photo 5 stained soil and unreported spill or leak.



Photo 6 Stained soil around crude oil tank.

Inspection Photos
Location Name: SRC Pratt pad
Location ID: 319098



Photo 7 flow lines not LOTO. Tag have no writing



Photo 8 Weeds on west side of location. Noxious weeds present.

Inspection Photos
Location Name: SRC Pratt pad
Location ID: 319098



Photo 9 location is eroding a channel off site carrying sediment off location. Also noxious weeds present.



Photo 10 sediment being carried off location

Inspection Photos
Location Name: SRC Pratt pad
Location ID: 319098



Photo 11 Noxious weeds



Photo 12 loc pic