

Inspection Photos
Location Name: McCallum Unit 178
Location ID: 324741



Photo 1. Overview of location taken facing north.



Inspection Photos
Location Name: McCallum Unit 178
Location ID: 324741



Photo 2. Wellhead inside housing.



Photo 3. Noxious weeds (Canada Thistle) on location.

