

Inspection Photos
Location Name: McCallum Unit 84
Location ID: 324645



Photo 1. Overview of location taken facing southeast.