

**Inspection Photos**  
**Location Name: McCallum Unit 182**  
**Location ID: 324744**



**Photo 1. Overview of location taken facing east.**



**Photo 2. Photo of wellhead inside housing cover. "Do not operate" tag on left.**

