

Inspection Photos

June 29, 2022

Operator: SWN Production Company LLC - #10396

Location ID: 313285

Location Name: Gulch-67N93W /21SESW

Inspection Document #: 702800408

Moffat County, CO

SESW Section 21 T7N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Gulch-67N93W /21SESW
Location ID: 313285



Photo 1. Photo taken from the southwest, at the Location entrance shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800408

Inspection Photos
Location Name: Gulch-67N93W /21SESW
Location ID: 313285



Photo 2. Photo taken from the east of the Location shows disturbed areas at the edge of the pad which are dominated by cheatgrass and require reclamation.



Photo 3. Photo taken from the east of the Location shows disturbed areas at the edge of the pad which appear to have been seeded with crested wheatgrass, a non-native perennial grass species not found in adjacent reference areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800408

Inspection Photos
Location Name: Gulch-67N93W /21SESW
Location ID: 313285



Photo 4. Photo taken from the center of the Location shows a soil compaction layer.



Photo 5. Photo taken in the undisturbed reference area to the south of the Location shows the soil structure lacks the compaction layer present on the Location.



Inspection Photos
Location Name: Gulch-67N93W /21SESW
Location ID: 313285



Photo 6. Photo taken from the south of the Location shows the reference area vegetation community is native rangeland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800408