

Inspection Photos

July 1, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 335228

Location Name: Benzel Disposal-66S93W /36NWNE

Inspection Document #: 702800410

Garfield County, CO

NWNE Section 36 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Benzel Disposal-66S93W /36NWNE

Location ID: 335228



Photo 1. Photo taken from the west of the Location shows an overview of the working pad area.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800410

Inspection Photos

Location Name: Benzel Disposal-66S93W /36NWNE

Location ID: 335228



Photo 2. Photo taken from the east of the Location shows a lack of stabilization/compaction degradation of the pad surface.




Photo 3. Photo taken from the southwest of the Location shows a lack of stabilization/compaction degradation of the access road.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800410

Inspection Photos

Location Name: Benzel Disposal-66S93W /36NWNE

Location ID: 335228



Photo 4. Photos taken from the southwest of the Location shows untreated Russian knapweed remaining in an area previously identified and recently treated.



Photo 5. Photo taken from the northwest of the Location shows a previously unidentified and untreated patch of Russian knapweed.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800410

Inspection Photos

Location Name: Benzel Disposal-66S93W /36NWNE

Location ID: 335228



Photo 6. Photo taken from the east of the Location shows an example of an area where subsidence has been filled.



Photo 7. Photo taken from the south of the Location shows where concrete forms have been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800410