

Inspection Photos

July 1, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 335385

Location Name: Benzel-66S93W /25SESW

Inspection Document #: 702800412

Garfield County, CO

SWNE Section 25 T6S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Benzel-66S93W /25SESW
Location ID: 335385



Photo 1. Photo taken from the north of the Location shows an overview of the working pad area.



Inspection Photos
Location Name: Benzel-66S93W /25SESW
Location ID: 335385



Photo 2. Photo taken from the east of the Location shows the fill slope and eastern interim area vegetated with the non-native perennial grass, crested wheatgrass.



Photo 3. Photo taken from the east of the Location shows the western interim area vegetated with the non-native perennial grass, smooth brome.

Inspection Photos
Location Name: Benzel-66S93W /25SESW
Location ID: 335385



Photo 4. Photo taken from the southwest of the Location shows a patch of Russian knapweed, a List B Noxious Weed. Inset shows a close-up up Russian knapweed plants.



Photo 5. Photo taken from the northeast of the Location shows a patch of Russian knapweed, a List B Noxious Weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800412