

Inspection Photos
Location Name: Spring Hollow Mac 1
Location ID: 325326



IMG 01
Well sign



IMG 02
Location overview



06Jul22 10:22 Ad-hoc
Hesperus CO 81326, United States © 06-Jul-22 10:22:59

IMG 03

Lube oil is impacting surface material



06Jul22 10:23 Ad-hoc
Hesperus CO 81326, United States © 06-Jul-22 10:23:26

IMG 04

Unused equipment and trash



IMG 05

Trash on west edge of location



IMG 06

Debris on southwest edge of location



IMG 07

Trash on east edge of location



IMG 08

Tank battery sign



IMG 09

Trash inside secondary containment



IMG 10

Unused equipment and trash



IMG 11

Bull plug is releasing oily residue and impacting material