


Inspection Photos
Location Name: Spring Hollow Mac 3
Location ID: 325648



IMG 01
Well sign



IMG 02
Location overview



IMG 03

Lube oil will soon begin to impact surface material



IMG 04

Lube oil has impacted surface material



IMG 05

Unused equipment



IMG 06

Unused empty drum



IMG 07

Flowline is not in use



IMG 08

2" black poly is not in use flow line or unused equipment