

**Inspection Photos**  
**Location Name: M and M 4**  
**Location ID: 215020**



**IMG 01**  
**Battery sign**



**IMG 02**  
**Trash inside secondary containment**



**IMG 03**  
**Unused empty drums**