

Inspection Photos

July 1, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 413683

Location Name: Youberg /SR 43-12

Inspection Document #: 702800421

Garfield County, CO

Lot 3 Section 7 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Youberg /SR 43-12
Location ID: 413683



Photo 1. Photo taken from the north shows an overview of the Location production area.



Photo 2. Photo taken from the north shows an overview of the Location production area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800421

Inspection Photos
Location Name: Youberg /SR 43-12
Location ID: 413683



Photo 3. Photo taken from the north shows the fill slope is well vegetated with perennial grasses. Stakes are present indicating areas of partial pad reconstruction.



Photo 4. Photo taken from the south shows the cut slope is well vegetated with perennial grasses.

Inspection Photos
Location Name: Youberg /SR 43-12
Location ID: 413683



Photo 5. Photo taken from the western interim area shows an example of bull thistle, a list B Noxious Weed present throughout the interim areas.



Photo 6. Photo taken from the western interim area shows an example of musk thistle, a list B Noxious Weed present throughout the interim areas.

Inspection Photos
Location Name: Youberg /SR 43-12
Location ID: 413683



Photo 7. Photos taken from the northern and southern interim area shows an example of spotted knapweed, a list B Noxious Weed present throughout the interim areas.

Inspection Photos
Location Name: Youberg /SR 43-12
Location ID: 413683



Photo 8. Photo taken at the west of the Location where pad reconstruction is planned shows the soil profile in a pit.