

Inspection Photos

July 1, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 323944

Location Name: Youberg-67S93W /7NWSW

Inspection Document #: 702800423

Garfield County, CO

NWSW Section 7 T7S R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Youberg-67S93W /7NWSW
Location ID: 323944



Photo 1. Photo taken from the southwest shows an overview of the Location.

Inspection Photos
Location Name: Youberg-67S93W /7NWSW
Location ID: 323944



Photo 2. Photo taken from the east of the Location shows interim areas and cut and fill slopes are well vegetated with smooth brome, a non-native perennial grass.

Inspection Photos
Location Name: Youberg-67S93W /7NWSW
Location ID: 323944



Photo 3. Photo taken from the north of the Location shows spotted knapweed, a CO List B Noxious Weed.



Photo 4. Photo taken from the fill slope at the north of the Location shows musk thistle, a CO List B Noxious Weed.

Inspection Photos
Location Name: Youberg-67S93W /7NWSW
Location ID: 323944



Photo 5. Photo taken at the north of the Location shows an anchor marker in disrepair.



Photo 6. Photo taken at the north of the Location shows an anchor marker in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800423

Inspection Photos
Location Name: Youberg-67S93W /7NWSW
Location ID: 323944



Photo 7. Photo taken from the north of the Location shows erosion degradation to the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800423