

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403085771

Date Received:

06/23/2022

Spill report taken by:

Brown, Kari

Spill/Release Point ID:

482371

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(970) 336-3500</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>(970) 515-1698</u>
Contact Person: <u>Gregory Hamilton</u>		Email: <u>Gregory_Hamilton@ox y.com</u>

Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 403076494

Initial Report Date: 06/13/2022 Date of Discovery: 06/13/2022 Spill Type: Historical Release

Spill/Release Point Location:

QTRQTR NWSE SEC 6 TWP 1N RNG 66W MERIDIAN 6

Latitude: 40.077534 Longitude: -104.818122

Municipality (if within municipal boundaries): Fort Lupton County: WELD

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No 318259
 Spill/Release Point Name: Deason William GU 1 Tank Battery Well API No. (Only if the reference facility is well) 05- -
 No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): <u>Unknown</u>	Estimated Condensate Spill Volume(bbl): <u>Unknown</u>
Estimated Flow Back Fluid Spill Volume(bbl): <u>0</u>	Estimated Produced Water Spill Volume(bbl): <u>Unknown</u>
Estimated Other E&P Waste Spill Volume(bbl): <u>0</u>	Estimated Drilling Fluid Spill Volume(bbl): <u>0</u>

Specify: _____

Has the subject Spill/Release been controlled at the time of reporting? Yes

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): _____

Weather Condition: Sunny, ~95 degrees F.

Surface Owner: FEE Other(Specify): _____

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On June 13, 2022, historical soil impacts were discovered during reclamation activities at the Deason William GU 1 O SA Production Facility. Excavation and assessment activities are ongoing. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):

OTHER NOTIFICATIONS

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
6/13/2022	City of Fort Lupton	T. Hodges	--email	
6/14/2022	Landowner	Private	--phone	
6/13/2022	Weld County	J. Maxey	--email	
6/13/2022	Weld County	R. Rudisill	--email	

REPORT CRITERIA

Rule 912.b.(1) Report to the Director (select all criteria that apply):

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: _____ Public Water System: _____
 Residence or Occupied Structure: _____ Livestock: _____
 Wildlife: _____ Publicly-Maintained Road: _____

No Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery _____ (HH:MM)
 Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 _____
 Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? _____
 Enter the Document Number of the Initial Accident Report, Form 22 _____
 Was there damage during excavation? _____
 Was CO 811 notified prior to excavation? _____

Yes Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): _____ 60

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

The presence of free product or hydrocarbon sheen Surface Water

The presence of free product or hydrocarbon sheen on Groundwater

The presence of contaminated soil in contact with Groundwater

The presence of contaminated soil in contact with Surface water

Yes Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylight from the subsurface.

No Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.

Areas offsite of Oil & Gas Location Off-Location Flowline right of way

No Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.

No Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: <u>06/21/2022</u>		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	_____	_____	<input checked="" type="checkbox"/>
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) Soil Groundwater Surface Water Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 5 Width of Impact (feet): 5

Depth of Impact (feet BGS): 1 Depth of Impact (inches BGS): _____

How was extent determined?

On June 13, 2022, historical soil impacts were discovered during reclamation activities at the previously decommissioned Deason William GU 1 O SA Production Facility, and excavation activities were initiated. On June 22, 2022, excavation and site assessment activities to address historical impacts were initiated and are currently ongoing. To-date, approximately 60 cubic yards of material have been removed and transported to the Front Range Landfill in Erie, Colorado for disposal. On June 22, 2022, preliminary soil and groundwater samples were collected from the site, and submitted for laboratory analysis of Table 915-1 constituents. Based on soil screening and field observations, the soil sample exhibiting the highest degree of impacts was selected for waste characterization purposes and was submitted for laboratory analysis of the full Table 915-1 analytical suite, using COGCC-approved methods appropriate for detecting the target analytes in Table 915-1. Subsequent confirmation soil samples will be submitted for the identified contaminants of concern, based on the initial waste characterization soil analytical results. The groundwater sample was submitted for laboratory analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, 1,2,4- and 1,3,5-trimethylbenzene (TMB), using standard methods appropriate for detecting the target analytes in Table 915-1. Analytical results for the samples collected on June 22, 2022 are currently pending laboratory analysis and reporting. Excavation and site assessment activities are ongoing and will be summarized in a forthcoming Form 19-Supplemental Spill/Release Report within 90-days of the release discovery date. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. Soil sample location and field screening data are provided in Table 1. Field notes and a photographic log are provided as Attachment A. The State Notification email is provided as Attachment B.

Soil/Geology Description:

Fat clay (CH)

Depth to Groundwater (feet BGS) 5

Number Water Wells within 1/2 mile radius: 94

If less than 1 mile, distance in feet to nearest

Water Well 290 None

Surface Water 70 None

Wetlands 70 None

Springs _____ None

Livestock 3350 None

Occupied Building 180 None

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 06/21/2022

Root Cause of Spill/Release Unknown (Historical)

Other (specify) _____

Type of Equipment at Point of Spill/Release: Other

If "Other" selected above, specify or describe here:

Tank Battery

Describe Incident & Root Cause (include specific equipment and point of failure)

Historical impacts were discovered during reclamation activities at the former production facility location.

Describe measures taken to prevent the problem(s) from reoccurring:

Site infrastructure has been removed and will not be replaced.

Volume of Soil Excavated (cubic yards): 60

Disposition of Excavated Soil (attach documentation) Offsite Disposal Onsite Treatment

Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): _____

Volume of Impacted Surface Water Removed (bbls): _____

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached, check all that apply)

Horizontal and Vertical extents of impacts have been delineated.

Documentation of compliance with Table 915-1 is attached.

All E&P Waste has been properly treated or disposed.

Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: _____

SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

OPERATOR COMMENTS:

Excavation and site assessment activities at this location are currently ongoing and will be summarized in a forthcoming Form 19- Supplemental Spill/Release Report within 90-days of the release discovery date.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Gregory Hamilton

Title: Environmental Consultant Date: 06/23/2022 Email: Gregory_Hamilton@oxy.com

Condition of Approval**COA Type****Description**

	Operator shall submit a site specific sampling analysis plan via Supplemental Form 19 once all laboratory analytical data has been received. Or Operator may analyze soil confirmation samples for all contaminants of concern in Table 915-1 in lieu of submitting a modified list for Director approval.
	Pursuant to Rule 912.b.(6) Operator is required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure pursuant to Rule 913.h and supported by adequate documentation to demonstrate that the Spill or Release has been fully cleaned up and complies with Table 915-1; or A Form 27 if any of the criteria listed in Rules 912.b.(6).B.i-iii apply. If Remediation will continue under an approved Form 27, the Operator will also submit a Form 19 – Supplemental which requests closure of the Spill or Release and includes the Remediation project number assigned by the Director.
2 COAs	

Attachment List**Att Doc Num****Name**

403085771	SPILL/RELEASE REPORT(SUPPLEMENTAL)
403085871	PHOTO DOCUMENTATION
403085872	TOPOGRAPHIC MAP
403085873	CORRESPONDENCE
403085884	OTHER
403099576	FORM 19 SUBMITTED

Total Attach: 6 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)