

Inspection Photos

API: 017-07224

Operator: GILBERT-STEWART OPERATING LLC

Inspection Date: 7/6/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-07224 | Date: 7/6/2022

Inspection Photos



Photo 1. Facing toward the well site. The 55 gal drum has fallen over. The emergency contact number is updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07224 | Date: 7/6/2022

Inspection Photos



Photo 2. It appears there was a spill from the 55 gal drum. Impacted soils will need to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07224 | Date: 7/6/2022