

# Inspection Photos

475565

Operator: GILBERT-STEWART OPERATING LLC

Inspection Date: 7/6/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing toward the tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

475565 | Date: 7/6/2022

## Inspection Photos



**Photo 2.** The berm around the tank battery is inadequate with animal burrows.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

475565 | Date: 7/6/2022

## Inspection Photos



**Photo 3.** There is unused equipment being stored at the location that needs to be removed. Pumpjack tanks, ect.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

475565 | Date: 7/6/2022

## Inspection Photos



**Photo 4.** There is a tote with plastic liner that needs to be removed. Weeds need to be controlled at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

475565 | Date: 7/6/2022