

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148




Photo 3 – Weeds



Photo 4 – Heater Treater

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148




Photo 5 – Unmarked Risers

Photo 6 – Gas Sales Line LOTO

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148




Photo 7 – Gas Calibration Card

Photo 8 – Pumping Unit

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 9 – Stained Soil at Wellhead




Photo 10 – Unused Equipment

Inspection Photos
Location Name: F Quarter Circle #1
Location ID: 327148



Photo 11 – Weeds



Photo 12 – Stained Soil and Unused Equipment