

Inspection Photos
Location Name: Anne Sate 9-7
Location ID: 329904



Colorado Oil and Gas Conservation Commission
40.23833, -104.24677, 4557.5ft, 152°
07/07/2022 12:28:00



Colorado Oil and Gas Conservation Commission
40.23823, -104.24668, 4562.3ft, 112°
07/07/2022 12:28:09

Photo 1 – Tank Battery

Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: Anne Sate 9-7
Location ID: 329904



Photo 3 – Wellhead



Photo 4 – Separator and Gas Meter

Inspection Photos
Location Name: Anne Sate 9-7
Location ID: 329904




Photo 5 – Gas Meter Calibration Card