

Inspection Photos
Location Name: Anne Sate 6
Location ID: 326750



Photo 1 – Tank Battery



Photo 2 – Tank Battery

Inspection Photos
Location Name: Anne Sate 6
Location ID: 326750



Photo 3 – Separator and ECD



Photo 4 – Gas Meter

Inspection Photos
Location Name: Anne Sate 6
Location ID: 326750



Photo 5 – Gas Meter Calibration Card



Photo 6 – Stained Soil

Inspection Photos
Location Name: Anne Sate 6
Location ID: 326750



Photo 7 – Wellhead




Photo 8 – Unused Equipment

Inspection Photos
Location Name: Anne Sate 6
Location ID: 326750



Photo 9 – Stained Soil