

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 1 – Tank Battery



Photo 2 – Tank Battery Sign

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 3 – Separator



Photo 4 – Gas Meter Calibration Card

Inspection Photos
Location Name: State 8-7
Location ID: 326971



Photo 5 – Stained Soil at North Tank



Photo 6 – Stained Soil at North Tank