

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7060 from entrance to location.



Photo #7061 from entrance to location.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7062 from entrance to location.



Photo #7063 from entrance to location.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7064 The pump was located just to the right of the rig at the time of the fire which was not compliant with COGCC rules.



Photo #7065 The pump is now located 30 to 40 feet further from the workover rig.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7072 Pump does not appear to have any damage from fire.



Photo #7073 Turbo side of pump.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7075 New location of rig tank.



Photo #7068 New location of pump.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7050 from Inspection #699804662. Original configuration of equipment at the time of the fire.

Photo #7063 New configuration of equipment.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7067 Turbo side of workover rig.



Photo #7069 Turbo side of workover rig.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7070 Turbo side of workover rig fire.



Photo #7054 cab side of workover rig fire from inspection #699804662 conducted on 6/30/22.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7074 New configuration of flow iron and hoses between pump and tank.



Photo #7071 production equipment from North West side of location.

Inspection Photos

Location Name: CHEVRON USA INC WILSON CREEK UNIT-62N94W /4NWSE

Location ID: 316060



Photo #7057 Production equipment from South West side of location. Photo from inspection #699804662 conducted on 6/30/22.