

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /10NENW

Location ID: 324107



Photo #7081 from entrance to location.



Photo #7083 Vent pipe open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /10NENW

Location ID: 324107



Photo #7084 Loadline open ended.