

## Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /10NENW

Location ID: 324107



**Photo #7077 from entrance to location.**



**Photo #7078 from entrance to location.**

## Inspection Photos

Location Name:TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /10NENW

Location ID: 324107



Photo #7079 Vent pipe on tank open ended.



Photo #7080 Loadline open ended.