

Inspection Photos

API: 017-06338

Operator: PINTAIL PETROLEUM LTD

Inspection Date: 7/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06338 | Date: 7/6/2022

Inspection Photos



Photo 1. Facing toward the well site. The soils appear to have been decompacted but crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06338 | Date: 7/6/2022

Inspection Photos



Photo 2. The soils appear to have been decompacted but crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-06338 | Date: 7/6/2022