

# Inspection Photos

API: 017-06815

Operator: CITATION OIL & GAS CORP

Inspection Date: 7/7/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06815 | Date: 7/7/2022

## Inspection Photos



**Photo 1.** Facing south toward the location. There are still areas that have not reestablished crop cover and there are undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06815 | Date: 7/7/2022

## Inspection Photos



**Photo 2.** Facing west toward the location. There are still areas that have not reestablished crop cover and there are undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06815 | Date: 7/7/2022

## Inspection Photos



**Photo 3.** Facing east toward the location. There are still areas that have not reestablished crop cover and there are undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-06815 | Date: 7/7/2022

## Inspection Photos



**Photo 4.** Facing toward the surrounding undisturbed crop cover.

