

Inspection Photos  
Location Name: Guildner 1  
Location ID: 317889



Photo 1 WH sign.

Photo 2 WH

Inspection Photos  
Location Name: Guildner 1  
Location ID: 317889



Photo 3 TB sign.

Photo 4 TB

**Inspection Photos**  
**Location Name: Guildner 1**  
**Location ID: 317889**



**Photo 5 Mechanical issue has been addressed and stained soil has been cleaned and removed by load out line.**

**Photo 6 Mechanical issue has been addressed and stained soil has been cleaned and removed by crude tank valve.**

Inspection Photos  
Location Name: Guildner 1  
Location ID: 317889



**Photo 7 Flow line manifold and HHS.**

**Photo 6 stained soil has been cleaned and removed from inside HHS housing.**