

BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770



Trash bag outside of pump shack. Unused supplies and equipment stored on location.

**BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770**



Pressure gauge is damaged.

**BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770**



Motor oil buckets no secondary containment.



Motor and lube oil staining ground under and around injection engine and pump.

**BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770**



Motor oil buckets no secondary containment.



Motor and lube oil staining ground under and around injection engine and pump.

**BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770**



**Unused supplies and equipment stored on location.
Chemical totes with no secondary containment.**



Unused supplies and equipment stored on location.

BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770



**BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770**



Deadmen markers not brightly colored.

Deadmen markers not brightly colored.

**BEEMAN OIL & GAS LLC
ELK SPRINGS UNIT-65N98W 30NWSE
Location # 311770**



Unmarked and damaged deadman in center of location.



Unmarked and damaged deadman in center of location.