

Inspection Photos
Location Name: Guttersen D09-745
API# 05-123-48941



Photo #1 Well



Photo #2 Stained Soil



Inspection Photos
Location Name: Guttersen D09-745
API# 05-123-48941



Photo #3 Stained Soil



Photo #4 Stained Soil

Inspection Photos
Location Name: Guttersen D09-745
API# 05-123-48941



Photo #5 Stained Soil



Photo #6 Stained Soil

Inspection Photos
Location Name: Guttersen D09-745
API# 05-123-48941



Photo #7 Trash



Photo #8 Unused Equipment “tote that is not hooked up”

