

**COLORADO OIL & GAS CONSERVATION CO
FIELD INSPECTION REPORT**



| | | | |
|---|------------------|---|--|
| <input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION | | 1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100 | |
| <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION | | | |
| API No. 05- 063 - 6246 | | LEASE NAME: COLMENO 12-30 #1 | |
| LOCATION: SWNW 30-115-50W | | OPERATOR: UPRC | |
| DATE: 7-27-95 | | INSPECTOR: R. VanSickle | |
| Insp. Type: PR | Insp. Status: PR | PA: Y N | Pass/Fail: (P) F Viol.: Y (N) NOV: Y N |

| INSPECTION ITEM | COMMENTS | INPUT |
|--|---|-------|
| Well ID Signs (Rule 210) | ✓ | |
| Pits (Reserve/Production) (Rule 902, 903, 904) | None | |
| Fences (Rule 604.C.(3), 1003.A) | N/A. | |
| Tank Battery Equipment (Rule 604) | 2400s, Pump unit, 400 BBL into th, sep., vert. H-T, GMR. | ✓ |
| Fire Walls/Berms/Dikes (Rule 604) | Adequate. | |
| General Housekeeping (Rule 603.G) | Good. | |
| Spills (Oil/Water) (Rule 908) | — | |
| Bradenhead (Rule 207) | — | |
| Drilling Well/Workover (Rule 315) | — | |
| Surface Rehabilitation (Rule 317) | — | |
| Miscellaneous | — | |

CORRECTIVE ACTION REQUIRED: None.

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.