



00511243



DEC 05 1994

WELL SITE INSPECTION FORM

Well Name Colmena 12-30 #1 API Number 05 - 063 - 6246
 Operator UPRC Permit # _____
 Location SWNW 30-115-50W County HIT CARSON
 Field HIGH POINT Inspector R. Wanglick

AL/PA/DA Inspection Results:

Well Status:

Pass(Y) _____ Fail(N) _____ Date _____ ND _____ DG _____ WO _____ PR ☒ SI _____ TA _____

Date of Inspection Before/During Drilling _____

Surf. Csg. Size _____ Setting Depth _____ Cmt. Vol. _____ WOC time _____
 Consistent with APD casing Program? YES _____ NO _____ Returns _____
 Rig _____ BOP'S _____ Stage Tool Depth _____ Cmt. Vol. _____

Date of Inspection Before/During/After Completion 10-31-94

Prod. Csg. Set? ☒ Completion Rig/Activity PR
 Drilling Pits: Closed ☒ Open _____ Wellhead Installed: ☒ Sign: Yes ☒ No _____
 Tank ID: Yes ☒ No _____ N/A _____ Skim Tank/Pit: 400 BBL Prod. Tanks: () _____ BBLs
 Equipment PU, VERT. HT. Meter Run: Yes _____ No ☒
 Bradenhead Press: _____ Fluid: No _____ Yes _____ Type _____ Well Cat. _____

AL/PA/DA Inspection

Date Plugged: _____ Date Permit Expired: _____
 Hole Plugged: Yes _____ No _____ Pits Backfilled: Yes _____ No _____
 Material Buried: Yes _____ No _____ N/A _____ Site Clean: Yes _____ No _____
 Bond Release OK: Yes _____ No _____ Fed _____ Hole Marker: Yes _____ No _____

Date of Safety/Status Inspection _____

Comments: Clear loc. Bty 200yds w. of well.

Violations: Yes _____ No _____ Notice Sent: Yes _____ No _____ Date Sent: _____