

Interim Reclamation and Stormwater Inspection

June 16, 2022

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 452516

Inspection Document #: 697504028

Weld County, CO

SESE Section 31 T12N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Oxnard East /0607-8CH
Location ID: 452516



Photo 1. Photo taken from the southeastern interim reclamation area, facing East. Photo illustrates Operator has responded to the previous corrective action to perform additional interim reclamation activities; however, there was little to no germination throughout the interim reclamation area.



Inspection Photos
Location Name: Oxnard East /0607-8CH
Location ID: 452516



Photo 2. Photo taken from the southeastern interim reclamation area, facing North. See comments under Photo 1.

Note: the Kochia seedlings are coming up in the drill rows, which is not desirable vegetation.



Photo 3. Photo taken from the eastern interim reclamation area, facing North. See comments under Photo 1.





Photo 4. Photo taken from the interim reclamation area. Photo illustrates that one of the desirable grass species was planted deeper than 1.5 inches. Native seeds should not be planted that deep and maybe why this attempt failed.

Inspection Photos
Location Name: Oxnard East /0607-8CH
Location ID: 452516



Photo 5. Photo taken from the northeastern interim reclamation area, facing North. See comments under Photo 1.



Photo 6. Photo taken from the northeastern interim reclamation area, facing West. See comments under Photo 1.