


Inspection Photos  
Location Name: Ellison 33-5 29-1  
Location ID: 378715



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**  
**Unused equipment**



**IMG 04**  
**Unmarked rig anchor**



**IMG 05**  
**Impacted material**



**IMG 06**  
**Weeds beginning to encroach interim revegetation**