

Inspection Photos

Location Name: Knight D 4

Location ID: 334012



IMG 01
Well signs



IMG 02
Location overview



IMG 03

Lube oil has begun to impact material



IMG 04

Lube oil has begun to impact material



IMG 05

Unused equipment



IMG 06

Stored supplies