

Inspection Photos
Location Name: Critter Creek /14 SESW
Location #: 444096



Photo #1
Critter Creek 521-1426H (05-123-42478)
Abandoned Location | AL
~ 215 yds.
No evidence of oil & gas activity
prior photo: 2021-07-30



Photo #2
Critter Creek 567-1411H (05-123-42481)
Abandoned Location | AL
~ 215 yds.
No evidence of oil & gas activity
prior photo: 2021-07-30

Inspection Photos
Location Name: Critter Creek /14 SESW
Location #: 444096



Photo #3
Critter Creek 520-1426H (05-123-42485)
Abandoned Location | AL
~ 215 yds.
No evidence of oil & gas activity
prior photo: 2021-07-30



Photo #4
Critter Creek 566-1411H (05-123-42533)
Abandoned Location | AL
~ 215 yds.
No evidence of oil & gas activity
prior photo: 2021-07-30