

Inspection Photos

API: 071-06762

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06762 | Date: 7/12/2022

Inspection Photos



Photo 1. Facing northeast along the main access road past the compressor. There is erosion along the roadside in this area and the culvert is partially filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 7/12/2022

Inspection Photos



Photo 2. Facing west along the main access road. There is erosion along the roadside in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 7/12/2022

Inspection Photos



Photo 3. The gate at the location needs to be reinstalled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 7/12/2022

Inspection Photos



Photo 4. Facing west toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06762 | Date: 7/12/2022