

Inspection Photos

API: 071-06704

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 7/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06704 | Date: 7/12/2022

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06704 | Date: 7/12/2022

Inspection Photos



Photo 2. There are noxious weeds that are wilted at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06704 | Date: 7/12/2022

Inspection Photos



Photo 3. Facing toward the well. The shed has been placed over the engine skid.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06704 | Date: 7/12/2022