

Inspection Photos

July 11, 2022

Operator: Peakview Operating Company LLC - #10409

Location ID: 435615

Location Name: Grassy Creek /13-26

Inspection Document #: 702800449

Routt County, CO

NWSW Section 26 T6N R87W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Grassy Creek /13-26
Location ID: 435615



Photo 1. Photo shows Location 435615 has not been built. There is no evidence of the abandoned location.

