

Inspection Photos and Issue Report

7/14/2022

Operator: EL PASO NATURAL GAS COMPANY -
26600

Location #382671
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: EL PASO NATURAL GAS COMPANY - 26600

Location #382671



Photo 1: Photos shows well marker has not been installed per (pre-1/15/2021 rule change) Rule 319.a.(5). Pipe has missing welded plate at top, and is currently open.

Inspection Photos

Operator Name: EL PASO NATURAL GAS COMPANY - 26600

Location #382671



Photo 2: Photos example showing noxious weed establishment observed on the Location, including Field Bindweed, Scotch thistle, Knapweed

Inspection Photos

Operator Name: EL PASO NATURAL GAS COMPANY - 26600

Location #382671



July 14, 2022



July 14, 2022

Photo 3: Photos example showing noxious weed establishment observed on the Location, including Field Bindweed, Scotch thistle, Knapweed