

Inspection Photos

July 11, 2022

Operator: Energy Investments Inc - #10469

Location ID: 316755

Location Name: Tow Creek-65N87W /11SWSW

Inspection Document #: 702800446

Moffat County, CO

SWSW Section 11 T5N R87W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Tow Creek-65N87W /11SWSW
Location ID: 316755



Photo 1. Photo taken from the Location entrance shows an overview of the northern portion of the Location.



Inspection Photos
Location Name: Tow Creek-65N87W /11SSW
Location ID: 316755



Photo 2. Photo taken from the east of the Location shows an overview of the northeastern portion of the Location.



Photo 3. Photo taken from the east of the Location shows an overview of the southeastern portion of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800446

Inspection Photos

Location Name: Tow Creek-65N87W /11SWSW

Location ID: 316755



Photo 4. Photo taken at the south of the Location shows an overview of the southwestern portion of the Location.



Photo 5. Photo taken at the west of the Location shows an overview of the northwestern portion of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800446

Inspection Photos
Location Name: Tow Creek-65N87W /11SWSW
Location ID: 316755



Photo 6. Photo taken at the southwest of the Location shows Canada thistle, a CO List B Noxious Weed.



Photo 7. Photo taken at the west of the Location shows musk thistle and houndstongue, CO List B Noxious Weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800446