

Inspection Photos

July 11, 2022

Operator: Energy Investments Inc - #10469

Location ID: 399383

Location Name: Wolf Mountain-67N87W /15NWSE

Inspection Document #: 702800448

Moffat County, CO

NWSE Section 15 T7N R87W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Wolf Mountain-67N87W /15NWSE
Location ID: 399383



Photo 1. Photo taken from the center of the Location shows the wellhead.



Photo 2. Photo taken from the center of the Location shows bull thistle, a CO List B Noxious Weed.

Inspection Photos
Location Name: Wolf Mountain-67N87W /15NWSE
Location ID: 399383



Photo 3. Photo taken from the east of the Location shows the northern production area. Red circle indicates the wellhead location.



Photo 4. Photo taken from the south of the Location shows where the tank battery was previously located.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800448

Inspection Photos
Location Name: Wolf Mountain-67N87W /15NWSE
Location ID: 399383



Photo 5. Photo taken from the east of the Location shows the northeastern portion of the Location.



Photo 6. Refer to Photo 5 comment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800448