

Inspection Photos

July 8, 2022

Operator: Quicksilver Resources Inc - #10255

Location ID: 312775

Location Name: Alpha-State-67N93W /16SESE

Inspection Document #: 702800426

Moffat County, CO

SESE Section 16 T7N R93W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Alpha-State-67N93W /16SESE
Location ID: 312775




Photo 1. Photo taken from the east shows an overview of the Location (outlined in red). A road runs through the center of the Location.



Inspection Photos
Location Name: Alpha-State-67N93W /16SESE
Location ID: 312775




Photo 2. Photo taken from the northwest of the Location shows the start of disturbed area vegetation monitoring transect #1.



Photo 3. Photo taken from the northwest of the Location shows the ground surface at the start of disturbed area vegetation monitoring transect #1.

Inspection Photos
Location Name: Alpha-State-67N93W /16SESE
Location ID: 312775



Photo 4. Photo taken from the west of the Location shows the end of disturbed area vegetation monitoring transect #1.



Photo 5. Photo taken from the west of the Location shows the ground surface at the end of disturbed area vegetation monitoring transect #1.



Inspection Photos
Location Name: Alpha-State-67N93W /16SESE
Location ID: 312775



Photo 6. Photo taken from the northeast of the Location shows the start of disturbed area vegetation monitoring transect #2.



Photo 7. Photo taken from the northeast of the Location shows the ground surface at the start of disturbed area vegetation monitoring transect #2.



Inspection Photos

Location Name: Alpha-State-67N93W /16SESE

Location ID: 312775



Photo 8. Photo taken from the east of the Location shows the end of disturbed area vegetation monitoring transect #2.



Photo 9. Photo taken from the east of the Location shows the ground surface at the end of disturbed area vegetation monitoring transect #2.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800426

Inspection Photos
Location Name: Alpha-State-67N93W /16SESE
Location ID: 312775



Photo 10. Photo taken from the adjacent reference area to the northwest of the Location shows the start of reference area vegetation monitoring transect #1.



Photo 11. Photo taken from the adjacent reference area to the northwest of the Location shows the ground surface at the start of reference area vegetation monitoring transect #1.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800426

Inspection Photos
Location Name: Alpha-State-67N93W /16SESE
Location ID: 312775



Photo 12. Photo taken to the northwest of the Location shows the end of reference area vegetation monitoring transect #1.



Photo 13. Photo taken to northwest of the Location shows the ground surface at the end of reference area vegetation monitoring transect #1.

