

Inspection Photos  
Location Name: Schuyler 34-9 30-2  
Location ID: 312037



IMG 01  
Well sign



IMG 02  
Location overview



**IMG 03**  
**Impacted material**




**IMG 04**  
**Impacted material**



IMG 05

Produced water tank sign



IMG 06

Fitting is releasing produced water