

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/15/2022

Submitted Date:

07/19/2022

Document Number:

701005423

FIELD INSPECTION FORM

Loc ID 321859 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 51065
Name of Operator: LOEB LLC* HERMAN L
Address: P O BOX 838
City: LAWRENCEVILLE State: IL Zip: 62439

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pelton, Shane	620-617-5870	shane@loeboil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208253	WELL	SI	08/14/2013	OW	017-07188	TEAGUE 34-13 3	PA

General Comment:

[P&A Inspection](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 208253 Type: WELL API Number: 017-07188 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Hurricane Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 5100/2150/1390/533

Cement Volume (sx): 323 SXS

Good Return During Job: YES

Cement Type: Class H Neat

Comment: PEAK WIRELINE, STERLING OILFIELD SERVICES, HALDE WATER, HURRICANE SERVICES. MIRU PEAK, RIH W/CIBP SET @ 5100' W/5 SXS CMT. PEAK, RIH W/CIBP SET @ 2150'. MIRU HURRICANE, TEST TO 300 PSIG. MIRU PEAK, RIH W/GUN, PERF @ 2100'. MIRU STERLING, RIH W/CICR. MIRU HURRICANE, PUMP 80 SXS CMT THRU W/5 SXS ON TOP. MIRU STERLING, POOH W/TBG. MIRU PEAK, RIH W/GUN, PERF @ 1390'. RIH W/GUN AND PERF @ 533'. MIRU STERLING, RIH W/CICR. MIRU HURRICANE, PUMP 50 SXS CMT THRU W/5 SXS ON TOP. MIRU STERLING, POOH W/TBG. MIRU HURRICANE, EST PRESSURE ON CSG. PUMP 183 SXS CMT W/CMT TO SFC.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT