

# Final Reclamation Inspection

July 13, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 332808

Inspection Document #: 697504063

Weld County, CO

SENE Section 28 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

# Inspection Photos

Location Name: WIEDEMAN J-65N66W 28SENE

Location ID: 332808



**Photo 1.** Google Earth aerial imagery from 9/12/2018 during active operations. Photo illustrates the well location and the associated offsite tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504063

# Inspection Photos

Location Name: WIEDEMAN J-65N66W 28SENE

Location ID: 332808



**Photo 2.** Photo taken from the southern well location, facing North. Photo illustrates crop growth is reflective of reference area crops; however, there are active remediation projects related to the the well and tank battery location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 697504063



## Inspection Photos

Location Name: WIEDEMAN J-65N66W 28SENE

Location ID: 332808



**Photo 3.** Photo taken of the associated offsite tank battery, facing West. Photo illustrates all equipment has been removed from location. The tank battery is not associated with crop production; therefore, there is no vegetation requirement. However, there is an open remediation project.



**Photo 4.** Photo taken of the associated offsite tank battery, facing North. See comments under Photo 3.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504063