

Inspection Photos
Location Name: Paul Schmidt GU B1
Location ID: 318587



Photo 1 WH sign.

Photo 2 WH.

Inspection Photos
Location Name: Paul Schmidt GU B1
Location ID: 318587



Photo 3 TB sign.

Photo 4 TB.



Inspection Photos
Location Name: Paul Schmidt GU B1
Location ID: 318587



Photo 5 HHS.

Photo 6 Gas Meter Run, card indicates current calibration.

Inspection Photos
Location Name: Paul Schmidt GU B1
Location ID: 318587



Photo 7 HHS.

Photo 8 Gas Meter Run, card indicates current calibration.