

Schell 12&13-5 O SA

Photographic Log

Remediation #21556

Facility Closure



EAGLE
ENVIRONMENTAL
CONSULTING, INC.

8000 W 44th Ave, Wheat Ridge, CO 80033
Ph: 303-433-0479 • F: 303-325-5449

Facility



Northern AST
AST= Above-Ground Storage Tank




AST surface sample locations looking northwest.

Facility



Separator base sample locations looking northwest



Produced water vessel sample locations

Facility



PH sampling locations looking northwest.



PH sampling locations looking east.

Facility



Meter house soil screening location looking northwest




Dump line screening location looking south.

Facility



Produced water background sample locations looking south.



Produced water excavation sample locations looking north.