



COLORADO OIL AND GAS CONSERVATION COMMISSION - UIC FIELD REPORT

FAC# 181 API# 001 06372 0 INSPECTOR L. Robbins DATE 3/8/89WELL NAME PONCHO UNIT 6 TYPE E SITE INSPECTION X

FIELD 69770 PONCHO STATUS TA WITNESS MIT

OPER 71450 PONCHO PRODUCTION CO

LOCATION NWNE 34 3.0S 59.0W 6

MAX PERMITTED PRESS 1659 PSI DATE LAST INSPECTION 08/11/88 OUTCOME A
LAST REPORTED PRESS PSI 09/87 DATE LAST MIT 00/00/00
WELL RESTRICTIONS WELL IS TO REMAIN SHUT-IN UNTIL IT PASSES AN MIT
REMEDIAL ACTION
COMPLETION TYPE TP

TUBING PRESSURE

ZONE JSND

MIT _____ INJECTING _____ PSI

P E R F S

MIT _____ NOT INJECTING 57 PSITOP 6094
BOT 6215

TUBING-CASING ANNULUS _____ PSI

BRAIDENHEAD _____ PSI

MECHANICAL INTEGRITY TEST

0 MIN. _____ PSI

5 MIN. _____ PSI

10 MIN. _____ PSI

15 MIN. _____ PSI

MIT
PACKER
DEPTH _____

PRESS CHANGE _____ PSI

CHART USED - YES _____ NO _____

ACCEPTABLE X NOT ACCEPTABLE _____

REMARKS: Flowline has been
disconnected from well
making it inoperable.
J Robbins

CASING
SIZE
DEPTH /SIZE
DEPTH /SIZE
DEPTH /SIZE
DEPTH /

PACKER

LINER
TOP
SIZE
DEPTH /PBTVD
TVDVED